


Push in Queen Introduction Cage




Material is 8 x 8 hardware cloth
----- Fold to 90 deg. in the order shown.
Tabs go outside and fasten with solder or epoxy

scale -1"=2"

Push in Queen Confinement Cage

Drawn by Gary S. Reuter
University of Minnesota
Dept. of Entomology
12-07-01



Material is 8 x 8 hardware cloth with the center cut out (5" x 12") and a piece of plastic or zinc queen excluder (6" x 13") fastened over it.


-Fold to 90 deg. in the order shown.

Tabs go outside and fasten with solder or epoxy

scale -1"=2"

Push in Queen Confinement Cage

Drawn by Gary S. Reuter
University of Minnesota
Dept. of Entomology
12-07-01



Material is 5 x 5 hardware cloth .
----- Fold to 90 deg. in the order shown.
Tabs go outside and fasten with solder or epoxy